

 <b>National Aeronautical Laboratory</b>	<b>Documentation Sheet</b>	<b>Document Classification</b> <b>Restricted</b>
<b>Title</b> : Study of White Patches on Nimonic 108 Turbine Blades		<b>Document No.</b> PD MT 8732  <b>Date of issue:</b> Oct. '87
<b>Author(s)</b> : A.C.Raghuram, S.Radhakrishnan, R.V.Krishnan, M.A.Venkataswamy and V.Ramachandran		<b>Contents</b> 1 page + 4 figures
<b>Division</b> : Materials Science		<b>No. of copies:</b> 12
<b>External participation</b> :		<b>NAL Project No.</b> MT-9-871, MT-1-167
<b>Sponsor</b> :		<b>Sponsor's Project No.</b>
<b>Approval</b> : A.C.Raghuram <span style="float: right;">28</span>		
<b>Remarks</b> :		
<b>Keywords</b> : Nimonic 108 turbine blades, white patches, carbon diffusion, chromium carbide precipitation, green rot.		
<b>Abstract</b> :  During heat treatment of Nimonic 108 turbine blades, white patches were formed on the aerofoil surface. Microstructure of the section through these patches indicated presence of chromium carbide precipitated along the grain boundaries. This is due to diffusion of carbon from the surface, at a high temperature for a prolonged time.		